Avolites LTD Engineering Change Notice

ECN title	Mobile Fader wing Ref Resistor		
ECN Number	ECN-198		
Related Product(s)	All Mobile fader wings up to SN		
Date / Author	24/04/2015	JB Toby	AVOLITES
Reasons for ECN	Warm environment may trigger stuck faders on the Fader wing		
Parts required	120R (0603) Avo PN 8000-1010 (kit of 3 resistors)		
Tools required	T20 screwdriver, small soldering iron, tweezers		
Estimated time	30 Minutes		

Background:

An increased temperature of the analog circuit inside the fader wing can cause the faders to never read zero, as a result playback faders are not released.

Warning. The ECN replace a 0603 size SMD resistor, this resistor is very small and specialist skills and tools are needed

The kit contains 3 resistors, however only one is fitted.

ECN procedure:


Disconnect the Mobile fader wing from the PC, Fit the white travel cover and place it upside down on a soft surface.


Remove the back lid (6x torks screws)






Locate R30 and remove it with a soldering iron, this is best done by swiping it towards the R30 legend (arrow)





Place a small amount of solder on the pad away from the R30 legend (arrow)



Using tweezers place the new resistor $(120R\ 0603)$ against the solder pad and reheat. Then solder the pad on the R30 side.

Connect the wing to a PC with USB expert running and check that the faders work and read zero when pulled down.

Close the console by refitting the lid

This concludes the ECN.