

**Avolites Ltd.**  
**Engineering Change Notice**

<b>Title</b>	INVC196 BOARD FUSE REPLACEMENT
<b>ECN Number</b>	ECN-0131
<b>Equipment</b>	INVC196 board
<b>Author</b>	JB Toby / Adam Proffitt
<b>Drawing Number</b>	
<b>Date</b>	18/10/00

<b>Reason for ECN</b>	Current surge ( $\approx 1A$ ) causes 500mA fuse to blow
<b>Special Parts required</b>	1.1A resetable fuse Avolites part number 10-02-0051
<b>Special Tools required</b>	None

<b>Work Required</b>
<p>Replace 500mA fuse on board with 1.1A resetable fuse/s</p>