

Avolites Ltd.  
Engineering Change Notice

Title Tonya3  
ECN Number: ECN-0108  
Equipment: Borris & Borris2 Mother Boards  
Date: 04/05/99  
Author: Adam Proffitt  
Revision: 1.0

Reason for ECN: Sometimes the desk will power up without all DMX lines operational.

Special Parts Required: Tonya 3 gal or programmer and jedec file (available from web site) for 20V8 gal.

Special Tools Required: None

Work Required:

Remove Tonya gal.  
Replace with Tonya 3.  
On Borris (not Borris2) Tonya is underneath the piggy-back board near the DMX connectors.