

**Avolites Ltd.**  
**Engineering Change Notice**

<b>Title</b>	Pearl 2000 Roller Modification.
<b>ECN Number</b>	ECN-0116
<b>Equipment</b>	
<b>Author</b>	Alwyn Fernandes
<b>Drawing Number</b>	
<b>Date</b>	18 <sup>th</sup> Feb 2000

<b>Reason for ECN</b>	Roller can sometimes become loose.
<b>Special Parts required</b>	Small sticker
<b>Special Tools required</b>	None

<b>Work Required</b>
<p>All Pearl 2000 rollers assembled at Alerhamblin will have a tamper proof sticker placed over one of the allen screws indicating it has been tightened - this should not be removed at Avolites. The remaining 3 screws should be checked for tightness.</p> <p>This modification should to implement with immediate effect.</p>