

Avolites Ltd.
Engineering Change Notice

Title	LCD Screens occasionally losing data
ECN Number	ECN-0138
Equipment	Sapphire 2000 Consoles
Author	Adam Proffitt
Drawing Number	none
Date	4 th July 2001

Reason for ECN	LCD Screens
Special Parts required	74LS374 - (05-03-0019)
Special Tools required	none

Work Required
<p>Very occasionally, the left two LCD screens on the Sapphire 2000 Memory Panel will appear to lose its data.</p> <p>This can be cured by changing component U6 from a 74HC374 to a 74LS374</p>