

Avolites Ltd.
Engineering Change Notice

Title ECN Number Equipment	Control fuse rating for ART2000 frames ECN-0130 ART 2000 48 Way frames using SPI 235W ATX PSU units
Author Drawing Number Date	J.B.Toby 27/09/00

Reason for ECN	Power rating increase of the ATX PSU as resulted in reports of nuisance tripping of control fuse at start up only
Special Parts required	5A T HBC fuse 20x5mm / fuse rating sticker Avolites part number 32-02-9001
Special Tools required	None

Work Required	
<p>Replace the control fuses with 5A T HBC fuses Situated to the right of the utility breakers</p> <p>Place "5A T HBC fuse " rating sticker over the "2 A Fuse" legend on the dimmer</p> <p>Sample of the legend:</p> <table border="1"><tr><td>5A T HBC fuse</td></tr></table>	5A T HBC fuse
5A T HBC fuse	