

Avolites Ltd.


Engineering Change Notice

Title	Azure Support Cable
ECN Number	ECN-0128
Equipment	Azure 2000 & Azure Shadow.
Author	Alwyn Fernandes
Drawing Number	17-02-0170A
Date	28/07/00


Reason for ECN	To stop the Azures from opening too far
Special Parts required	
Special Tools required	None

Work Required

The length of the Azure Support cable is critical. It has to be exactly 520mm long – see drawing 17-02-0170A for further details.
Both the fixing points have now changed for this cable – this are indicated below.



Top right hand side



Bottom right corner