

Avolites Ltd.
Engineering Change Notice

Title	ART2000 T2 and T4 J1/J2 connector mating
ECN Number	ECN-0154
Equipment	ART2000 T2 and T4 frames
Author	J.B.Toby
Drawing Number	
Date	23/2/2004

Reason for ECN	Some channels do not work after transport of the frame. Channels can be made to work by re-seating the controller. This is due to the J1/J2 connector not mating properly
Special Parts required	J1/J2 spacer Avolites no. 1322-0215AA
Special Tools required	None

Work Required

1. Disconnect the dimmer frame from power
2. remove the controller
3. for the T2, remove the top flight case lid
for the T4 remove the top-patch panel
4. Unscrew the 4 2.5 nuts holding the J1/J2 connector
5. place the spacer according to picture below (holes facing up)
6. refit the J1/J2 connector and M2.5 screws / nuts
7. refit the controller and test the system

Avolites Ltd.
Engineering Change Notice

